

George A. Pecoraro et al.,
METHODS OF ADJUSTING GLASS MELTING DEFORMING
TEM TURES WITHOUT SUBSTANTIALLY CHAIR G BENDING AND
ANNEALING TEMPERATURES AND GLASS ARTICLES PRODUCED THEREBY
Sheet 1 of 3



George A. Pecoraro et al.

METHODS OF ADJUSTING GLASS MELTING FORMING
TEMPE URES WITHOUT SUBSTANTIALLY CHANGE BENDING AND
ANNEALL TEMPERATURES AND GLASS ARTICLES FADDUCED THEREBY



George A. Pecoraro et al.
METHODS OF ADJUSTING GLASS MELTING VD FORMING
TEN TURES WITHOUT SUBSTANTIALLY CHARGE BENDING AND
ANNEAL OF TEMPERATURES AND GLASS ARTICLES PRODUCED THEREBY
Sheet 3 of 3

